


# Grinding screwdrivers




GRIND WHEN TIP IS THIN—

①




WHEN TIP IS BEVELED—

②



WHEN TIP IS ROUNDED

③





FOR JOINTING:

HOLD SCREW DRIVER AT  
LEVEL OF CENTER OF STONE

N.B. MOVE SCREW DRIVER  
RIGHT AND LEFT  
*To Avoid uneven wear on stone!*



④



MOVE RIGHT & LEFT

GRIND UNTIL SIDES ARE PARALLEL  
AND FIT SCREW SLOT —

⑤



MOVE RIGHT & LEFT  
AND UP & DOWN

OR UNTIL SIDES ARE NEARLY PARALLEL  
AND FIT SCREW SLOT

⑥

A SUGGESTION



CONCAVE



STRAIGHT

LEAVE SHANK AS STRONG  
AS POSSIBLE

⑦



THIS TYPE  
NEEDS NO  
SHARPENING

⑧